

# PASSAGES DE COSSES

PPE0301

## Mécatraction

ELP



FLP



TRS



TN



## Passage possible dans les Presse Etoupes (mini)

Cosse ELP	PE mini	Cosse TRS	PE mini	Cosse TN	PE mini	Cosse TN	PE mini
ELP40	M20 N6	TRS95-10	M32 N8	TN25-5	M20 N6	TN120-10	M40 N9
ELP50	M20 N6	TRS95-12	M32 N8	TN25-6	M20 N6	TN120-12	M40 N9
ELP60	M20 N6	TRS446-10	M32 N8	TN25-8	M20 N6	TN120-14	M40 N9
ELP80	M20 N6	TRS446-12	M32 N8	TN25-10	M25 N7	TN120-16	M40 N9
ELP100	M25 N7	TRS446-14	M32 N8	TN35-6	M25 N7	TN150-10	M40 N9
ELP120	M25 N7	TRS448-10	M32 N8	TN35-8	M25 N7	TN150-12	M40 N9
ELPU40	M20 N6	TRS448-12	M32 N8	TN35-10	M25 N7	TN150-14	M40 N9
ELPU50	M20 N6	TRS448-14	M32 N8	TN50-6	M25 N7	TN150-16	M40 N9
ESPU50	M20 N6	TRS450	M40 N9	TN50-8	M25 N7	TN150-18	M40 N9
		TRS450-14	M40 N9	TN50-10	M25 N7	TN185-12	M50 N10
		TRS452-12	M40 N9	TN50-12	M25 N7	TN185-14	M50 N10
		TRS452	M40 N9	TN60-8	M32 N8	TN185-16	M50 N10
		TRS452-16	M40 N9	TN60-10	M32 N8	TN185-18	M50 N10
		TRS4520BL	M40 N9	TN60-12	M32 N8	TN240-14	M50 N10
		TRS455	M40 N9	TN70-8	M32 N8	TN240-16	M50 N10
		TRS455-12PE	M40 N9	TN70-10	M32 N8	TN240-18	M50 N10
				TN70-12	M32 N8	TN240-20	M50 N10
				TN95-10	M32 N8	TN300-16	M63 N12
				TN95-12	M32 N8	TN300-18	M63 N12
				TN95-14	M32 N8	TN300-20	M63 N12
						TN300-22	M63 N12

## Principe du Passage de Cosses

